

PP-3 Guard Tour Verification

Easy to use:

- No cumbersome cables or download cradle required.

Connectivity:

- Downloads directly to PC or mobile device via Bluetooth.
- Records can be sent directly to the cloud.

Durability:

- Long-life, compact, and very robust.
- One year hardware guarantee against defects.

Compatibility:

- TGII & QuikReports software compatible with Microsoft Windows 10 OS and above. (Not: Apple iOS/MAC OS)
- Mobile download application is however Apple iOS compatible for in-field cellular and/or Wi-Fi download capability by enabled Apple and/or Android devices.



Authorized **DETEX** Distributor



RFID Tags:


- 30mm wall mount checkpoints
- Pocket incident wallet with 12 checkpoints
- KeyFob for keychain
- Badge Card
- Value assigned in TGII software: Tour start point, tour checkpoint, incident, personnel



TGII – Software (PC)



Active Protective Case w/Lanyard
(stays on PP-3 while reading)



Mobile App



PP-3 Recorder



PP-3 Recorder Specifications:

- **Casing:** Glass Reinforced Polycarbonate
- **Power:** 3 "AAA" standard batteries (available at any store)
- **Memory:** Battery-supported RAM, 5040 records
- **Dimensions:** L 4" x W 1.9" x H 1.4" inches / 10.0 x 4.8 x 3.5 cm
- **Weight:** .4 lbs. / 160 grams
- **Durability:** PCB designed to last over 10 years, capable of withstanding shocks and tropical rainforest conditions.
- **Operating Conditions:** Temperature -40° to 85°C, Humidity above 90% RH

TGII Software:

- Easy-to-use
- PDF report of all recorded tour data with each download/export.
- Reports can be stored locally, anywhere on client network and/or in cloud.

Hardware ID	QR No.	Site Name	Tour	Checkpoint Name	Date / Time	Officer	Message
de00000059def024	36000001c404e803	XYZ Shopping Mall	North Wing	001 - Entrance	2021-08-11 16:14:10	Mr William Orange	
de00000059def024	5700000180542f04	XYZ Shopping Mall	North Wing	002 - Nightingale Bank	2021-08-11 17:17:20	Mr William Orange	
de00000059def024	23000001a2c73704	XYZ Shopping Mall	North Wing	004 - Childrens Corner	2021-08-11 18:16:12	Mr William Orange	
de00000059def024	ba000001b2825404	XYZ Shopping Mall	North Wing	006 - Barber Shop	2021-08-11 18:21:39	Mr William Orange	
de00000059def024	ba000001b2825404	XYZ Shopping Mall	North Wing	006 - Barber Shop	2021-08-11 18:25:43	Mr William Orange	
de00000059def024	ba000001b2825404	XYZ Shopping Mall	North Wing	006 - Barber Shop	2021-08-11 18:25:51	Mr William Orange	Fire Hazard
Report: 36000001c404e803 : Duration 0 Days - 2 Hours - 11 Minutes - 41 Seconds : (2021-08-11 16:14:10 - 2021-08-11 18:25:51) : Omissions: 2 : 003 - The Acupuncture/005 - Phone Fix							
de00000059def024	36000001c404e803	XYZ Shopping Mall	North Wing	001 - Entrance	2021-08-11 18:28:02	Mr Charles Zapodilla	
de00000059def024	5700000180542f04	XYZ Shopping Mall	North Wing	002 - Nightingale Bank	2021-08-11 18:40:34	Mr Charles Zapodilla	
de00000059def024	81000001c46eaa04	XYZ Shopping Mall	North Wing	003 - The Acupuncture	2021-08-11 18:55:03	Mr Charles Zapodilla	
de00000059def024	81000001c46eaa04	XYZ Shopping Mall	North Wing	003 - The Acupuncture	2021-08-11 18:55:12	Mr Charles Zapodilla	Gas Leak
de00000059def024	23000001a2c73704	XYZ Shopping Mall	North Wing	004 - Childrens Corner	2021-08-11 19:09:20	Mr Charles Zapodilla	
de00000059def024	23000001a2c73704	XYZ Shopping Mall	North Wing	004 - Childrens Corner	2021-08-11 19:09:54	Mr Charles Zapodilla	Fire Alarm
de00000059def024	cb000001c5007c04	XYZ Shopping Mall	North Wing	005 - Phone Fix	2021-08-11 19:13:03	Mr Charles Zapodilla	
de00000059def024	ba000001b2825404	XYZ Shopping Mall	North Wing	006 - Barber Shop	2021-08-11 19:15:33	Mr Charles Zapodilla	
Report: 36000001c404e803 : Duration 0 Days - 0 Hours - 47 Minutes - 31 Seconds : (2021-08-11 18:28:02 - 2021-08-11 19:15:33) : Omissions: 0 :							
de00000059def024	6c00000127051703	Test Site 54	Zulu Assembly Plant	001 - Helicopter Hangar	2021-08-12 16:14:22	-	
de00000059def024	c1000001272f8404	Test Site 54	Zulu Assembly Plant	002 - Engine Works	2021-08-12 16:29:47	Mr Charles Zapodilla	
de00000059def024	c1000001272f8404	Test Site 54	Zulu Assembly Plant	002 - Engine Works	2021-08-12 16:30:07	Mr Charles Zapodilla	Fire Alarm
Report: 6c00000127051703 : Duration 0 Days - 0 Hours - 15 Minutes - 45 Seconds : (2021-08-12 16:14:22 - 2021-08-12 16:30:07) : Omissions: 4 : 003 - Avionics/004 - Paint Shop/005 - Structures/006 - Wind Tunnel							

QuikReports Software:

- Powerful SQL database engine to generate comprehensive and/or filtered reports on all collected data.
- View missed tour checkpoints.
- Required to create report by date range from multiple TGII export downloads filterable by site, guard, tour, etc.
- Enables report generation from anywhere within the client environment: with network and/or with cloud access to TGII created database.

(718) 784-4900

www.CentralTimeClock.com

Central Time Clock, Inc. · 5-23 50th Avenue · Long Island City, NY 11101 USA